


MIWA Q68046 LAMP SOCKET AND SOCKET ASSEMBLY Filed: January 11, 2002 Darryl Mexic 202-293-7060 1 of 6





MIWA Q68046 LAMP SOCKET AND SOCKET ASSEMBLY Filed: January 11, 2002 Darryl Mexic 202-293-7060 2 of 6





MIWA Q68046 LAMP SOCKET AND SOCKET ASSEMBLY Filed: January 11, 2002 Darryl Mexic 202-293-7060 3 of 6





MIWA Q68046 LAMP SOCKET AND SOCKET ASSEMBLY Filed: January 11, 2002 Darryl Mexic 202-293-7060 4 of 6




FIG.6

MIWA Q68046 LAMP SOCKET AND SOCKET ASSEMBLY Filed: January 11, 2002 Darryl Mexic 202-293-7060 5 of 6

